







|             |                 |
|-------------|-----------------|
| Printed:    | Plantno.: KTA 1 |
| Function: = |                 |
| Place: +    |                 |

|         |       |
|---------|-------|
| Page: 2 | of 11 |
|---------|-------|






|  |     |           |        |         |         |          |                 |            |                 |
|--|-----|-----------|--------|---------|---------|----------|-----------------|------------|-----------------|
|  | Rev | Date      | Drawer | Constr. | Control | Customer | Farnell         | Printed:   | PlantNo.: KTA 1 |
|  |     | 5-12-2007 |        | MHB     |         | Place    |                 |            |                 |
|  |     | 6-12-2007 |        |         |         | Plant    |                 | Function.: |                 |
|  |     |           |        |         |         | Item     | CONTROL DIAGRAM | Place:     | Page: 4 of 11   |
|  |     |           |        |         |         |          |                 |            |                 |











|  |     |            |        |         |         |          |                       |              |                 |
|--|-----|------------|--------|---------|---------|----------|-----------------------|--------------|-----------------|
|  | Rev | Date       | Drawer | Constr. | Control | Customer | Farnell               | Printed:     | Plantno.: KTA 1 |
|  |     | 5-12-2007  |        | MHB     |         | Place    |                       |              |                 |
|  |     | 20-08-2008 |        |         |         | Plant    |                       | Function.: = |                 |
|  |     |            |        |         |         | Item     | DRAWING OF KOMPONENTS | Place: +     | Page: 10 of 11  |